# IV. HETEROGENEOUS DATA

## A. PLUTONIUM SYSTEMS

1. Correlation Between Calculation and Experiment
2. Critical Sphere Dimensions
3. Critical Cylinder Parameters
4. Critical Slab Parameters
5. Critical Sphere Mass
6. Critical Sphere Volume
7. Material Bucklings and Extrapolation Distances